

HOW TO MAKE SFMEA?

- 1 functional
- 2 interface
- 3 deramiled
- 4 usability



- 5 vulnerability
- 6 serviceability
- 7 serviceability
- 8 production

CHOOSE VIEWPOINT




DEFINE FAILURE "FAILURE"



WRITE THE CAUSES




DESCRIBE THE EFFECTS OF THE FAILURE



EYE S, O and optionally D

- S - severity
- O - occurrenence
- D - detectability



BASED ON THE SELECTED RISK INDICATOR, MAKE DECISIONS ON OPTIMIZATION